

Informace o dosavadním pokroku v šetření

Drážní inspekce v souladu s § 53b odst. 1 zákona č. 266/1994 Sb., o dráhách, ve znění pozdějších předpisů (dále jen zákon č. 266/1994 Sb.), zahájila dne 10. 10. 2022 šetření příčin a okolností vzniku mimořádné události ze dne 7. 10. 2022, kdy v 9:05 h na dráze železniční, kategorie celostátní, na železničním přejezdu P3585, v km 312,048, mezi železničními stanicemi Libice nad Cidlinou a Poděbrady došlo ke střetnutí soupravy posunu mezi dopravnými jedoucí po vyloučené koleji s osobním automobilem.

V souladu s § 53e odst. 2 zákona č. 266/1994 Sb. Drážní inspekce zveřejňuje informace o dosavadním pokroku v šetření a podstatných otázkách, které jsou jeho předmětem. V rámci šetření výše uvedené mimořádné události bylo doposud učiněno:

- analýza zápisu o ohledání místa mimořádné události včetně zúčastněných drážních vozidel, technických zařízení a infrastruktury dráhy sepsaného provozovatelem dráhy;
- dodatečné ohledání místa vzniku MU Drážní inspekcí, měření parametrů železničního přejezdu a rozhledových poměrů;
- zadání 3D skenování místa přejezdu P3585;
- ověřovací pokus, kterým byl ověřen a obrazově zdokumentován rozhled řidiče automobilu jedoucího přes železniční přejezd v daném směru;
- zadání podrobné analýzy záznamu rychloměrného proužku mechanického registračního rychloměru zúčastněného hnacího drážního vozidla;
- analýza podání vysvětlení zúčastněných a svědků;
- analýza výsledků komisionální prohlídky zúčastněných drážních vozidel;
- analýza dalších podkladů vyžádaných od provozovatele dráhy, dopravce a Policie ČR;
- zadání zpracování simulace dle dostupných údajů o pohybu vlaku a automobilu s cílem určit možnost spatření drážního vozidla ze strany řidiče automobilu.

Information about the investigation progress

Date of the occurrence: 7th October 2022.

Location: open line between Libice nad Cidlinou and Poděbrady stations, level crossing No. P3585, km 312,048.

Description: collision of the shunting between operating control points with a car at the level crossing No. 3585.

ID of the occurrence: CZ-10317.

As part of the investigation of the above-mentioned occurrence, it has been done so far:

- analysis of the record about examination of the occurrence location including participating rolling stocks, technical devices and infrastructure written by IM;
- additional examination of the occurrence location by NIB, measuring of the level crossing parameters and limits of visibility;
- assignment of 3D scan of the level crossing No. P3585;
- verification trial, which verified and visually documented the view of a car driver driving across a level crossing;
- assignment a detailed analysis of the record of the speedometer strip of the mechanical registration speedometer of the participating locomotive;
- give explanations of the participating employee and witnesses;
- analysis of results of commission inspection of the participating rolling stocks;
- analysis documentation from IM, RU and Police of the Czech Republic;
- assignment of simulation processing according to the available data on the movement of the train and the car in order to determine the possibility of seeing the rolling stock by the car driver.